Airframe Log Entry N13DK S/N002
3-03-2012 1489.67TT
Performed Annual inspection IAW Extra Service Manual chap. 5 100 Hr items. Tested and inspected ELT IAW FAR 91.207 (d), treated and primed area of small paint corrosion on lower fuselage below battery box, Treated and primed chaffed area on fuselage adjacent to left side rear seatbelt attachment. Conducted visual inspection of entire fuselage, Cleaned and repacked wheel bearings, flipped main tires upon reassembly, Complied with the following AD's, 98-24-07, 10-04-11, 05-11-07, 76-07-12. No other AD's due at this time. Post engine ground run and system operational checks were satisfactory. I certify this Airframe has been inspected IAW and Annual Inspection and is in an Airworthy condition.
Stroube W. Lander II
2877274 IA

Wartungsarbeiten, Teilüberholungen
100-Std.-Nachprüfungen, angeordnete Nachprüfungen