FACTORY BULLETINS	_	ν S S	and ion.	
	_	OK S/N002 TSN IAW Extra Service No defects noted,	has been inspected IAW and d is in an Airworthy condition. ४८ हो	
Propeller Log Entry N13DK	_	/N002 Extra S efects r	ctec thy	
Removed this propeller S/N 95018 from N663JC EA300L	_	S/N S/N S/Ex	inspecte Airworthy	
S/N 020 @ 215.51 TTSN. The Propeller and Engine were installed on aircraft N13DK EA300L S/N 002 with 1417.27	_	3DK S 91TSN on IAW is. No d	en in an Ai	-
TT. The propeller and engine were not separated during this	_	V13[87.91 ction ems.	bee in a	
removal. The propeller operation was checked after installation. No defects noted. **The first operation was checked after installation. No defects noted. **Stroube W. Lander II 2877274IA 8-1-2011	-	Propeller Log Entry N13DK S/N00 3-03-2012 1489.67TT 287.91TSN Propeller S/N 95282 Performed Annual Inspection IAW Extra Manual chap 5 100 Hr items. No defects AD's at this time. I certify this propeller has been inspected Annual Inspection and is in an Airworthy Stroube W. Lander II		
-	_	T () T T Z <	1 - 4 V/00 K	© ASA 19