

ACTT: 210.23
Lycoming AEIO-540-L1B5, s/n L-25731-48A

Performed 100 hour/annual inspection IAW Extra Service Manual chapter 5 Time Limits/Maintenance checks.

AD 2008-14-07 Fuel injector lines c/w IAW Lycoming MSB 342E. Next due 310.23 hours


Changed oil and filter. New CH48109 filter installed and serviced with 12 quarts Shell 15W-50 oil.


Compression: #1: 78/80 #2: 78/80
 #3: 74/80 #4: 79/80
 #5: 78/80 #6: 78/80

Ground run, ops checks, and leak checks good.

I CERTIFY THAT THIS ENGINE
HAS BEEN INSPECTED IN ACCORDANCE WITH A(N)
100 HR/ANNUAL INSPECTION AND WAS DETERMINED
TO BE IN AN AIRWORTHY CONDITION.

ACTT 210.23 DATE 26 May 2010


FRANK E. CECILIA A&P 3439119 IA

N663JC EA300L
S/N 25731-48A J
Performed 100 H
manual P/N 0670
Changed oil and f
compression wit
#3 78/90, #4 79/8
Complied with th
IAW Lycoming M
was ground run a
I certify that has
Annual inspecti
Airworthy cond

Stroube W Lane
AP 2877274IA
June 16 2011