ENGIN	<u>E LOG</u>
DV	

Engine Log Entry N13DK 231.61 TSN, 1433.37 TTAF Removed engine driven fuel pump P/N RG9080J4A S/N D5474. Installed serviceable repaired fuel pump P/N RG9080J4A/M S/N D8509 (see 8130-3). AD 2003-14-03 is

no longer applicable to this pump. Installed Casper Labs oil filter adapter STC SE01930NY IAW service instructions manual # CL1000A. See 337 this date. Equipment list was updated. Weight and balance change is negligible. Engine was ground run and checked for leaks, no defects noted.

Thoulele Jander II
Stroube W. Lander II

2877274IA 8-16-2011

G	Serial N Signature	TO ALIGITY S.
IARKS	Signature	N. S.
2		

All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.